

# Oil Field Environmental Incident Summary

**Incident:** 20150322170548

**Date/Time of Notice:** 03/22/2015 17:05

**Responsible Party:** MUREX PETROLEUM CORPORATION

**Well Operator:** MUREX PETROLEUM CORPORATION

**Well Name:** MAXWELL JAMES 17-20H

**Field Name:** STANLEY

**Well File #:** 24109

**Date Incident:** 3/21/2015

**Time Incident:** 18:34

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 155

**Rng:** 91

**Sec:** 17

**Qtr:** NW NE

**Location Description:**

**Submitted By:** William Jansky

**Received By:**

**Contact Person:** Shannon Holter  
363 N. Sam Houston Pkwy. E.  
Suite 200  
HOUSTON, TX 77060

**General Land Use:** Cultivated

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 2500 Feet

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	40	Barrels			40	barrels
Other						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 3/11/2016

**Clean Up Concluded:** 9/1/2015

**Risk Evaluation:**

None

**Areal Extent:**

Spill impacted the soil to the northeast of site. approximately 50-75 feet off of location.

**Potential Environmental Impacts:**

release impacted soil adjacent to a wetland. The impacted area will need to be diked and cleanup start immediately to prevent wetland contamination.

**Action Taken or Planned:**

The leaking getty box valve was closed and valve on tank was also closed. Communicate with vendors that both valves need to be closed.

**Wastes Disposal Location:** TBD.

**Agencies Involved:**

**Updates**

---

**Date:** 3/23/2015    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release due to leak at the getty box. Flow/spray off location. Wetland threatened. Followup is necessary.

---

**Date:** 3/24/2015    **Status:** Inspection

**Author:** Wax, Pete

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On site 1200, off site 12:40. Snowing, 32 degrees, wind 5 mph from NE. Spill traveled north off well pad into agricultural field, then east, then southeast for a total distance of approximately 250 feet. Cleanup activities in progress at time of inspection. Cleanup included diking at head of spill to prevent further spreading and also harvesting of impacted soils. Leading edge of spill lies with 10 meters of the western edge of a wetland. Spill does not appear to have reached the wetland, and chloride tests support that hypothesis. Needs followup to ensure no legacy impacts to agricultural field.

---

**Date:** 9/1/2015      **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location 12:22 9/1/2015.

No sign of residual impacts off of location. Vegetation has regrown in area, and adjacent field has a good crop.

No followup is necessary.